



IMPORTANT SAFETY RECALL

August 17, 2015

Subject: Britax ClickTight Convertible Recall 15C-003
Products included in recall: Certain Advocate ClickTight, Boulevard ClickTight, and Marathon ClickTight Model Convertible Car Seats

This notice is sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Dear Britax Consumer:

Britax Child Safety, Inc., in cooperation with the National Highway Traffic Safety Administration and Transport Canada, is conducting a recall of certain Advocate ClickTight, Boulevard ClickTight, and Marathon ClickTight model convertible car seats. Britax has decided that these models manufactured between August 1, 2014 and July 29, 2015 may contain a defect with the harness adjuster button (red), which would pose a safety hazard. The car seats and model numbers included in this recall are identified in the table below.

| | |
|--|--|
| | <p><u>Advocate ClickTight:</u> E1A025Q ADVOCATE CT XE CIRCA E9LT95N ADVOCATE CT US, TAHOE E9LT95Q ADVOCATE CT US, CIRCA E9LT95Z ADVOCATE CT US, LIMELIGHT</p> |
| | <p><u>Boulevard ClickTight:</u> E1A015Q BOULEVARD CT XE CIRCA E1A016A BOULEVARD CT XE KALEIDOSCOPE E1A016H BOULEVARD CT XE METRO E1A135Q BOULEVARD CT US UCS, CIRCA E9LT85Q BOULEVARD CT US, CIRCA E9LT85S BOULEVARD CT US, SPLASH E9LT86A BOULEVARD CT US, KALEIDOSCOPE E9LT86F BOULEVARD CT US UCS, BLAKENEY E9LT86G BOULEVARD CT US UCS, WESTIN E9LT86H BOULEVARD CT US, METRO</p> |
| | <p><u>Marathon ClickTight:</u> E1A005R MARATHON CT XE VERVE E1A006B MARATHON CT XE TWILIGHT E1A116L MARATHON CT TARGET, VIBE E9LT71Q MARATHON CT US, COWMOOFLAGE E9LT75R MARATHON CT US, VERVE E9LT76B MARATHON CT US, TWILIGHT E9LT76L MARATHON CT US, VIBE E9LT76N MARATHON CT US, RIO E9LT76P MARATHON CT US UCS, PRESCOTT EXA116L MARATHON CT US, VIBE</p> |



ONLY THE SEATS WITH THIS CLICKTIGHT DIAL ARE INCLUDED IN THE RECALL.
NOTE: No other ClickTight products are included in this recall. If your Britax product has a different model number than the model numbers listed above, it is NOT included in this recall.

Description of the Defect

The ClickTight model convertible car seats identified in the table above have harness adjuster buttons (red) which may remain down in the “release” position after the harness is tightened. This will enable the shoulder harnesses to loosen from a child’s movements while secured in the seat. A loose harness may not adequately protect a child in the event of a motor vehicle crash.

Remedy of the Defect

To remedy this condition, we are providing you this free kit that includes a non-toxic food-grade lubricant to apply directly to the harness adjuster button (red). After this one-time application of lubricant, the adjuster button will function normally, move freely inside the finger guide, and will not remain down in the “release” position after the harness is tightened.

What You Should Do

Follow the instructions included in the remedy kit. We recommend that you apply the lubricant to the harness adjuster button (red) immediately. If you have any questions, contact our Customer Service Department at 1-888-427-4829 (choose option 3) or for consumers outside of US and Canada please call 704-409-1699 or email Britax.Recall@britax.com.

To view a video on how to remedy your car seat, visit www.BritaxClickTightConvertibleRecall.com.

If you are having difficulty getting your car seat remedied within a reasonable amount of time and without charge, you may write to the following address:

For US Consumers:

Administrator

National Highway Traffic Safety Administration

1200 New Jersey Ave, S.E.

Washington, D.C. 20590

Or you may call the toll free Vehicle Safety

Hotline at 1-888-327-4236 or (TTY: 1-800-424-9153)

Or visit www.safercar.gov and search

Recall ID: 15C-003

Sincerely,

Britax Child Safety, Inc.

Britax Child Safety, Inc.
4140 Pleasant Rd.
Fort Mill, SC 29708
USA

A Britax Childcare Group Ltd. company

Tel: 704-409-1700
Fax: 704-409-1710

P04344500